

# Handling instructions

# **SELF-ADHESIVE PROFILES (SOLID, SPONGE, CO-EX)**

Management of self-adhesive profiles (SA profiles) must conform to industry standards. Particular attention should be paid to:

### 1. Proper storage

1.1. SA profiles must be stored indoors, kept at temperatures 21  $\pm 5$  °C and relative humidity of 50 %, for the period not exceeding 6 months. SA profiles must be stored in their original packaging.

#### 2. Usage

2.1. SA profiles must be applied to clean, dry, greaseless and dustless surfaces. Temperature at adhesion must be between 15 °C and 30 °C. When assembling SA Profiles, adhesive tape should only be used as an aid.

## 3. Cleaning

3.1. SA profiles must be cleaned with window cleaning solutions which are generally available on the market, including retail stores.

#### **Contact:**

Phone: +386 4 206 60 80 Fax: +386 4 206 5475 Email: TSP.SLO@trelleborg.com

Internet: <a href="https://www.trelleborg.com/en/seals-and-profiles/">https://www.trelleborg.com/en/seals-and-profiles/</a>

resources/general-sales-conditions

# Address:

Trelleborg Slovenija d.o.o. Profiles Programme Škofjeloška cesta 6 4000 Kranj, Slovenia