

Trelleborg – High Impact and abrasion rubber wear liners were installed in a Caterpillar AD 45 B dump truck body. These dump Trucks carry ore from underground to above surface. Trelleborg Liners reduce carry back but protect the truck body from aggressive wear, improve OH&S, and allow the mine improved availability due to reduction in maintenance downtime.