

PERFORMER CERAMIC

Case study

Ovako, steel mill, Sweden

Application

Pneumatic injection of coke into the steel furnace.

Previous hose


Ceramic hose competitor with ball cylinders ceramic.
Lifespan: 12 weeks.

Installation date of PERFORMER CERAMIC hose

Week 23 - 2017 (June)
PERFORMER CERAMIC DN=50mm.

Lifespan

PERFORMER CERAMIC has been replaced week 8 - 2018
(February) and has been working for 32 weeks.



PERFORMER CERAMIC on field

BENEFITS HIGHLIGHTED BY CUSTOMER

Much longer lifespan vs ceramic hose competitor.



PERFORMER CERAMIC hose inside after 32 weeks of use